

2005 Ford Ranger

2.3 cylinder head

2.5 short block

VIN

1FTYR10D05PB10515

OBD codes from my reader

P0023-

Camshaft position actuator, exhaust/right,Rear Bank 2

Circuit malfunction

C2500

Charging system (Multimeter shows charging well

C2007

Antilock warning ABS

B3307

Harness shorted

P0755

Shift Solenoid shift circuit B Malfunction

P0750

Shift Solenoid shift circuit A Malfunction

P0743

Torque Converter Clutch solenoid (electrical malfunction)

P00B8

MAF sensor or VAF sensor correlation bank 2

Short in wiring loom????

Defective ECU????